



WD36 WD30  
WD35 WD29

T13N R15W  
T13N R15W

WD30 WD24  
WD29 WD23

T13N  
T13N

81-290  
31.40 Ac.  
NW Pt.

OR272-597  
Frac. 8 Pt.

OR272-597  
Frac. 4

Larry & Pamela Long  
OR357-89  
72.2954 Ac.  
NW Pt.  
230003070101

OR272-597  
Frac. 3

Robert & Rebecca Theller  
OR361-124  
32.3303 Ac.  
NW Pt.,  
N 1/2 SW Pt.  
230003070100

82-69  
80.18 Ac.  
S 1/2 NW Pt.

375.00 Ac.  
Frac. 1, 2, 3, 4, 8 Pt.

U.S.A.  
86.86 Ac.  
04366000

T13N R15W  
T13N R15W

OR230-684  
3.64 Ac.

U.S.A.  
Tot. 653.35 Ac.  
170004126000

T13N R15W  
T13N R15W

-340  
69 Ac.  
7 Pt.

Twp. Trustees  
(Cemetery)  
170004366100

64-73  
2.50 Ac.

79-486  
80.00 Ac.  
N 1/2 SW

OR272-597  
Frac. 2 Pt.

OR272-597  
Frac. 2 Pt.

K J Restoration, LLC  
OR359-504  
39.9819 Ac.  
NW Pt.,  
N 1/2 SW Pt.  
230003070102

Frac. 5 Pt.

72-340  
33.13 Ac.

OR272-597  
Frac. 1

Donald Bennett  
OR96-653 \*  
Tot. 2.65 Ac.  
(Stanley & Mary Bennett, LE)  
230003180000

1.15 Ac.  
(calc.)  
5 Ac.

Theodore Robinson  
196-506  
3.02 Ac.  
230003180000

216-342  
25.00 Ac.  
Frac. 5 Pt.

79-489  
25.00 Ac.  
S 1/2 S 1/2 SW

U.S.A.  
107-200 \*  
72.18 Ac.  
S 1/2 SW Pt.  
230003186000

WD35 WD29  
WD34 WD28

T13N R15W  
T13N R15W

WD29 WD23  
WD28 WD22

0100

U.S.A.  
Tot. Sec. 137.33 Ac.

OR272-597  
Frac. 4  
230002676000