


REFERENCE POINT #1
 IRON PIN
 STA. 308+93.25, 19.30' LT.
 ELEV. 772.69
 NORTHING: 527811.0391
 EASTING: 2008466.8559



REFERENCE POINT #2
 IRON PIN
 STA. 313+65.35, 32.08' RT.
 ELEV. 769.64
 NORTHING: 528153.6156
 EASTING: 2008796.8754

SR 328 CENTERLINE COORDINATES		
STATION	NORTHING	EASTING
PC 308+20.00	527744.9055	2008430.6880
PT 310+61.21	527927.1066	2008588.4994
PC 312+90.14	528109.5746	2008726.7538
PT 315+07.10	528294.8223	2008838.9382
PC 315+98.66	528377.6336	2008877.9885
PT 318+01.35	528574.9728	2008911.7954
POT 318+16.97	528590.5200	2008910.2150

CHANNEL BASELINE COORDINATES		
STATION	NORTHING	EASTING
POT 0+25	528100.2114	2008811.4059
PI 1+24.47	528143.4581	2008721.8243
PI 1+46.11	528158.4874	2008706.2594
POT 1+75	528184.9930	2008694.7687

CALCULATED
 JAMW
 CHECKED
 SWL

REFERENCE POINTS
 CENTERLINE COORDINATES (HOC-328-5.93)

HOC-328-2.70/5.93