



199-474
41.35 Ac.
SE SE
08000480006

199-474
12.00 Ac.
W 1/2 SW Pt.

210-303
43.00 Ac.
SE SW Pt.
08000345000

145-98
44.01 Ac.
SE SE

145-98
40.00 Ac.

Jeffrey
Kreashbaum
198-377
5.17 Ac.
08000348000

89-547, 5.00 Ac.
E 1/2 SW Pt.

LA21
LA28

LA22
LA27

LA22
LA27

LA23
LA26

5.72 Ac.
W 1/2 NW Pt.

107-671
1.00 Ac.
Linn & Nancy
Altman
08000393000

Nancy Altman, et al
210-303
67.00 Ac.
E 1/2 NW Pt.
W 1/2 NE Pt.
08000392000

John Huffines
OR133-71
Tot. 11.43 Ac.
5.72 Ac.
W 1/2 NW Pt.
080003910400

Goldia Rowland
202-80
5.72 Ac.
W 1/2 NW Pt.
080003910300

Harold Rowland
OR94-387
5.72 Ac.
W 1/2 NW Pt.
080003910200

John & Judy
Rowland
216-775
5.72 Ac.
W 1/2 NW Pt.
080003910000

207-193
100.00 Ac.
E 1/2 NW Pt.
W 1/2 NE Pt.
080003900000

Crane Hollow, Inc.
Tot. 153.57 Ac.

89-492
80.00 Ac.
E 1/2 NE

88-260
41.00 Ac.
NW NW Pt.

88-
28.00
NE N

201-751
80.03 Ac.
E 1/2 NE
080004060000

201-751
53.57 Ac.
W 1/2 NW Pt.
080003910100

Crane Hollow,
Inc.
Tot. 353.22 Ac.

89-492
41.00 Ac.
SW NW

88-
41.00
SE N

T12N R18W
T12N R18W

T12N R18W
T12N R18W

201-751
40.01 Ac.
NE SE
080004060000

Lucas & Lynn
Horn
OR121-595
82.00 Ac.
W 1/2 SW
080003890000

State Of Ohio
Tot. 327.50 Ac.
080003946000

89-492
42.00 Ac.
NE SE

89-492
41.00 Ac.
NW SW

88-
41.00
NW

Lucas & Lynn Horn
OR121-595
30.00 Ac.
SE SE Pt.
080004010000

61-9
81.50 Ac.
E 1/2 SW Pt.

Michael & Nancy
Downey
OR211-612
080003940000

61-9
82.00 Ac.
W 1/2 SE

146-335
42.00 Ac.
SE SE

146-335
42.00 Ac.
SW SW

90-1
40.08
SE S

194-13
15.00 Ac.
SE SE Pt.
080004030000

LA28
LA33

LA27
LA34

T12N R18W
T12N R18W

LA27
LA34

LA26
LA35

Lucas & Lynn
Horn
OR121-595
30.00 Ac.

State of Ohio