



Betty & Robert Sparks  
OR484-191  
16.46 Ac.  
SE SE Pt.  
130000430000

OR111-544  
SW SW  
36.00 Ac.  
130000220000

Tot. 77.4974 Ac.

Tot. 58.92 Ac.

James Moses  
196-127  
Tot. 33.01 Ac.  
130000310000

Tot. 36.83 Ac.  
130000330000

Richard Smoot  
Tot. 82.87 Ac.  
OR255-793  
30.27 Ac.  
130000120000

Stephenson  
OR97-673  
2.50 Ac.  
130000120100

130000010000

PE03 PE02  
PE10 PE11

PE02 PE01  
PE11 PE12

OR111-544  
SW SW  
36.00 Ac.  
130000220000

200-771  
33.53 Ac.  
SE SW Pt.  
130000340000

T12N R19W  
T12N R19W

25.50 Ac.  
SE SE Pt.

Richard Smoot  
Tot. Sec. 22.13 Ac.  
OR255-793  
5.03 Ac.  
130001910400

OR325-215, OR312-457  
1.21 Ac.  
130000120300

OR80-103  
9.50 Ac.  
Frac. 6 Pt.  
130000010100

HIDDEN LAKES ASSOCIATION  
Lots 1-24  
130001500000

Robert & Gayle Moses  
OR111-544  
37.00 Ac.  
NW NW  
130001800000

John & Clara Cavinee  
200-771  
31.24 Ac.  
NE NW Pt.  
130001840000

Ronald & Susan Colby  
OR524-108  
47.785 Ac.  
W 1/2 NE Pt.  
130001810000

5.002 Ac. (CT)  
130001810100

Danny Demint  
144-203  
40.00 Ac.  
NE NE  
130001900000

Richard Smoot  
Tot. Sec. 22.13 Ac.  
OR255-793  
8.79 Ac.  
Frac. 2 Pt.  
130001910100

Robert Robinson  
OR241-887  
5.00 Ac.  
130001910000

J. Bro  
OR30  
14.7  
Frac.  
13000

130001500000  
HIDDEN LAKES ASSOCIATION  
OR134-396  
182-41  
192-492  
33.67 Ac. \*

5.00 Ac.  
W NW Pt.

39.00 Ac.  
SW NW Pt.

Etta Hartshorn  
149-13  
8.67 Ac. \*  
130001850000

Robert E. Sr. & Marcia R. Jessberger, Trustees  
OR319-247, 0188 Ac.  
130001720000

Donald & Catherine Hill  
OR148-896  
33.94 Ac.  
Frac. 2 Pt.  
130001910300

Billie Riddleberger  
OR477-267  
5.00 Ac.  
130001910200

Constance Ramey  
OR329-147  
5.04 Ac.  
Frac. 2 Pt.  
130001940000

Mark Bailey  
174-214, 5.03 Ac.  
Frac. 2 Pt. (CT)  
130001930000

John Jr. & Kim Kouger  
OR362-273  
41.77 Ac.  
NE Pt.  
130001480000

Marcia & Robert Sr. Jessberger, Trustees  
OR468-817  
Tot. 71.66 Ac.  
130001790000

27.66 Ac.  
SE NW Pt.

Lisa Siemer  
185-891  
2.0445 Ac.  
130001770400

Abdul & Erum Oayum  
OR518-196  
Tot. 9.945 Ac. (Including Lot 27)  
130001810200

Debra & David McDaniel  
OR215-604  
39.94 Ac.  
SE NE Pt.  
130001710000

Donald & Catherine Hill  
OR148-896, .06 Ac.  
130001700000

210-273, 5.68 Ac.  
N 1/2 NW Pt., Frac. 1 Pt.  
130002020100

Mark & Elizabeth Bailey  
Tot. 11.15 Ac.

OR42-153  
11.18 Ac.  
130001450101

Ryan P. Cunningham, Trustee  
OR523-645  
Tot. Sec. 19.684 Ac.  
19.494 Ac.  
NE SE Pt.  
130001470100

219-333, 217-154  
20.00 Ac.  
N 1/2 NW SW  
130001690000

Dewey Bias  
Tot. 78.90 Ac.  
219-333, 217-154  
33.90 Ac.  
NE SW Pt.  
130001690000

Christina Siemer  
185-897, 2.056 Ac.  
130001770100

H. Rocky Marcum  
OR22-948  
Tot. Sec. 50.73 Ac.  
35.00 Ac.  
NE SE Pt.  
130001860100

Debra & David McDaniel  
OR244-305  
3.670 Ac.  
130002020400

Kyle & Lauree Althous  
OR534-432  
Tot. 12.637 Ac.  
5.001 Ac.  
SW NW Pt.  
130002040200

Brian Bowman  
OR26-511  
32.00 Ac.  
Frac. 1 Pt.  
130001970401

OR42-153  
11.18 Ac.  
130001450101

John Jr. & Kim Kouger  
OR362-273  
41.77 Ac.  
NE Pt.  
130001480000

Marcia & Robert Sr. Jessberger, Trustees  
OR468-817  
Tot. 71.66 Ac.  
130001790000

Ronald & Marjorie Reed (T.O.D. OR490-955)  
OR490-953  
6.868 Ac.  
130001780100

Abbeyhills Sub. No. 1  
Lots 1-14  
No Plat Book D, Pg. 41  
No Plat Cab. 1, pg. 87 A

Debra & David McDaniel  
OR244-305  
3.670 Ac.  
130002020400

Debra & David McDaniel  
OR244-305  
3.670 Ac.  
130002020400

Michael J. Bowe  
Tot. 9.490 Ac.  
130002020500

T & D Properties, L  
Tot. 117.04175 Ac

OR42-153  
11.18 Ac.  
130001450101

Ryan P. Cunningham, Trustee  
OR523-645  
Tot. Sec. 19.684 Ac.  
19.494 Ac.  
NE SE Pt.  
130001470100

219-333, 217-154  
20.00 Ac.  
N 1/2 NW SW  
130001690000

Dewey Bias  
Tot. 78.90 Ac.  
219-333, 217-154  
33.90 Ac.  
NE SW Pt.  
130001690000

Oscar Morrison  
OR210-56  
40.00 Ac.  
NW SE  
130001720000

H. Rocky Marcum  
OR22-948  
Tot. Sec. 50.73 Ac.  
35.00 Ac.  
NE SE Pt.  
130001860100

Robert & Karen Thompson  
OR94-765  
9.00 Ac.  
NW SW Pt.  
130002060000

Thomas Vance  
OR530-529, OR420-399  
Tot. 15.44 Ac. \*  
130002030000

OR451-600  
39.09375 Ac.  
NE SW Pt.  
130001970400

OR42-153  
11.18 Ac.  
130001450101

Ryan P. Cunningham, Trustee  
OR523-645  
Tot. Sec. 19.684 Ac.  
19.494 Ac.  
NE SE Pt.  
130001470100

219-333, 217-154  
20.00 Ac.  
N 1/2 NW SW  
130001690000

Dewey Bias  
Tot. 78.90 Ac.  
219-333, 217-154  
33.90 Ac.  
NE SW Pt.  
130001690000

Oscar Morrison  
OR210-56  
40.00 Ac.  
NW SE  
130001720000

H. Rocky Marcum  
OR22-948  
Tot. Sec. 50.73 Ac.  
35.00 Ac.  
NE SE Pt.  
130001860100

Robert & Karen Thompson  
OR94-765  
9.00 Ac.  
NW SW Pt.  
130002060000

Thomas Vance  
OR530-529, OR420-399  
Tot. 15.44 Ac. \*  
130002030000

OR451-600  
39.09375 Ac.  
NE SW Pt.  
130001970400

OR42-153  
11.18 Ac.  
130001450101

Ryan P. Cunningham, Trustee  
OR523-645  
Tot. Sec. 19.684 Ac.  
19.494 Ac.  
NE SE Pt.  
130001470100

219-333, 217-154  
20.00 Ac.  
N 1/2 NW SW  
130001690000

Dewey Bias  
Tot. 78.90 Ac.  
219-333, 217-154  
33.90 Ac.  
NE SW Pt.  
130001690000

Oscar Morrison  
OR210-56  
40.00 Ac.  
NW SE  
130001720000

H. Rocky Marcum  
OR22-948  
Tot. Sec. 50.73 Ac.  
35.00 Ac.  
NE SE Pt.  
130001860100

Robert & Karen Thompson  
OR94-765  
9.00 Ac.  
NW SW Pt.  
130002060000

Thomas Vance  
OR530-529, OR420-399  
Tot. 15.44 Ac. \*  
130002030000

OR451-600  
39.09375 Ac.  
NE SW Pt.  
130001970400

OR42-153  
11.18 Ac.  
130001450101

Ryan P. Cunningham, Trustee  
OR523-645  
Tot. Sec. 19.684 Ac.  
19.494 Ac.  
NE SE Pt.  
130001470100

219-333, 217-154  
20.00 Ac.  
N 1/2 NW SW  
130001690000

Dewey Bias  
Tot. 78.90 Ac.  
219-333, 217-154  
33.90 Ac.  
NE SW Pt.  
130001690000

Oscar Morrison  
OR210-56  
40.00 Ac.  
NW SE  
130001720000

H. Rocky Marcum  
OR22-948  
Tot. Sec. 50.73 Ac.  
35.00 Ac.  
NE SE Pt.  
130001860100

Robert & Karen Thompson  
OR94-765  
9.00 Ac.  
NW SW Pt.  
130002060000

Thomas Vance  
OR530-529, OR420-399  
Tot. 15.44 Ac. \*  
130002030000

OR451-600  
39.09375 Ac.  
NE SW Pt.  
130001970400

OR42-153  
11.18 Ac.  
130001450101

Ryan P. Cunningham, Trustee  
OR523-645  
Tot. Sec. 19.684 Ac.  
19.494 Ac.  
NE SE Pt.  
130001470100

219-333, 217-154  
20.00 Ac.  
N 1/2 NW SW  
130001690000

Dewey Bias  
Tot. 78.90 Ac.  
219-333, 217-154  
33.90 Ac.  
NE SW Pt.  
130001690000

Oscar Morrison  
OR210-56  
40.00 Ac.  
NW SE  
130001720000

H. Rocky Marcum  
OR22-948  
Tot. Sec. 50.73 Ac.  
35.00 Ac.  
NE SE Pt.  
130001860100

Robert & Karen Thompson  
OR94-765  
9.00 Ac.  
NW SW Pt.  
130002060000

Thomas Vance  
OR530-529, OR420-399  
Tot. 15.44 Ac. \*  
130002030000

OR451-600  
39.09375 Ac.  
NE SW Pt.  
130001970400

OR42-153  
11.18 Ac.  
130001450101

Ryan P. Cunningham, Trustee  
OR523-645  
Tot. Sec. 19.684 Ac.  
19.494 Ac.  
NE SE Pt.  
130001470100

219-333, 217-154  
20.00 Ac.  
N 1/2 NW SW  
130001690000

Dewey Bias  
Tot. 78.90 Ac.  
219-333, 217-154  
33.90 Ac.  
NE SW Pt.  
130001690000

Oscar Morrison  
OR210-56  
40.00 Ac.  
NW SE  
130001720000

H. Rocky Marcum  
OR22-948  
Tot. Sec. 50.73 Ac.  
35.00 Ac.  
NE SE Pt.  
130001860100

Robert & Karen Thompson  
OR94-765  
9.00 Ac.  
NW SW Pt.  
130002060000

Thomas Vance  
OR530-529, OR420-399  
Tot. 15.44 Ac. \*  
130002030000

OR451-600  
39.09375 Ac.  
NE SW Pt.  
130001970400

OR42-153  
11.18 Ac.  
130001450101

Ryan P. Cunningham, Trustee  
OR523-645  
Tot. Sec. 19.684 Ac.  
19.494 Ac.  
NE SE Pt.  
130001470100

219-333, 217-154  
20.00 Ac.  
N 1/2 NW SW  
130001690000

Dewey Bias  
Tot. 78.90 Ac.  
219-333, 217-154  
33.90 Ac.  
NE SW Pt.  
130001690000

Oscar Morrison  
OR210-56  
40.00 Ac.  
NW SE  
130001720000

H. Rocky Marcum  
OR22-948  
Tot. Sec. 50.73 Ac.  
35.00 Ac.  
NE SE Pt.  
130001860100

Robert & Karen Thompson  
OR94-765  
9.00 Ac.  
NW SW Pt.  
130002060000

Thomas Vance  
OR530-529, OR420-399  
Tot. 15.44 Ac. \*  
130002030000

OR451-600  
39.09375 Ac.  
NE SW Pt.  
130001970400

OR42-153  
11.18 Ac.  
130001450101

Ryan P. Cunningham, Trustee  
OR523-645  
Tot. Sec. 19.684 Ac.  
19.494 Ac.  
NE SE Pt.  
130001470100

219-333, 217-154  
20.00 Ac.  
N 1/2 NW SW  
130001690000

Dewey Bias  
Tot. 78.90 Ac.  
219-333, 217-154  
33.90 Ac.  
NE SW Pt.  
130001690000

Oscar Morrison  
OR210-56  
40.00 Ac.  
NW SE  
130001720000

H. Rocky Marcum  
OR22-948  
Tot. Sec. 50.73 Ac.  
35.00 Ac.  
NE SE Pt.  
130001860100

Robert & Karen Thompson  
OR94-765  
9.00 Ac.  
NW SW Pt.  
130002060000

Thomas Vance  
OR530-529, OR420-399  
Tot. 15.44 Ac. \*  
130002030000

OR451-600  
39.09375 Ac.  
NE SW Pt.  
130001970400

OR42-153  
11.18 Ac.  
130001450101

Ryan P. Cunningham, Trustee  
OR523-645  
Tot. Sec. 19.684 Ac.  
19.494 Ac.  
NE SE Pt.  
130001470100

219-333, 217-154  
20.00 Ac.  
N 1/2 NW SW  
130001690000

Dewey Bias  
Tot. 78.90 Ac.  
219-333, 217-154  
33.90 Ac.  
NE SW Pt.  
130001690000

Oscar Morrison  
OR210-56  
40.00 Ac.  
NW SE  
130001720000

H. Rocky Marcum  
OR22-948  
Tot. Sec. 50.73 Ac.  
35.00 Ac.  
NE SE Pt.  
130001860100

Robert & Karen Thompson  
OR94-765  
9.00 Ac.  
NW SW Pt.  
130002060000

Thomas Vance  
OR530-529, OR420-399  
Tot. 15.44 Ac. \*  
130002030000

OR451-600  
39.09375 Ac.  
NE SW Pt.  
130001970400

OR42-153  
11.18 Ac.  
130001450101

Ryan P. Cunningham, Trustee  
OR523-645  
Tot. Sec. 19.684 Ac.  
19.494 Ac.  
NE SE Pt.  
130001470100

219-333, 217-154  
20.00 Ac.  
N 1/2 NW SW  
130001690000

Dewey Bias  
Tot. 78.90 Ac.  
219-333, 217-154  
33.90 Ac.  
NE SW Pt.  
130001690000

Oscar Morrison  
OR210-56  
40.00 Ac.  
NW SE  
130001720000

H. Rocky Marcum  
OR22-948  
Tot. Sec. 50.73 Ac.  
35.00 Ac.  
NE SE Pt.  
130001860100

Robert & Karen Thompson  
OR94-765  
9.00 Ac.  
NW SW Pt.  
130002060000

Thomas Vance  
OR530-529, OR420-399  
Tot. 15.44 Ac. \*  
130002030000

OR451-600  
39.09375 Ac.  
NE SW Pt.  
130001970400

OR42-153  
11.18 Ac.  
130001450101

Ryan P. Cunningham, Trustee  
OR523-645  
Tot. Sec. 19.684 Ac.  
19.494 Ac.  
NE SE Pt.  
130001470100

219-333, 217-154  
20.00 Ac.  
N 1/2 NW SW  
130001690000

Dewey Bias  
Tot. 78.90 Ac.  
219-333, 217-154  
33.90 Ac.  
NE SW Pt.  
130001690000

Oscar Morrison  
OR210-56  
40.00 Ac.  
NW SE  
130001720000

H. Rocky Marcum  
OR22-948  
Tot. Sec. 50.73 Ac.  
35.00 Ac.  
NE SE Pt.  
1300